



Serie 250 bar

Pressione max esercizio bar	Tipo Type	Size	D	E	A	H	OR O-RINGS
250	O.2617	3/8"	24,5	6,7	18	15	3068
250	O.2621	1/2"	30,2	6,7	24	16	4075
250	O.2627	3/4"	38,1	6,7	31,5	17	4100
250	O.2633	1"	44,4	8	38	19	4131
250	O.2642	1" 1/4	50,8	8	43	23	4150
250	O.2649	1" 1/2	60,3	8	50	26	4187
250	O.2660	2"	71,4	9,5	62	31	4225
250	O.2675	2" 1/2	87,2	12	76	37	4275
250	O.2690	3"	101,6	15	90	42	4337
250	O.2603	3" 1/2	119	20	102	54	6337
250	O.2615	4"	131	23,5	114	62	6387
250	O.2640	5"	155	23,5	141	62	201

Serie 400 bar

Pressione max esercizio bar	Tipo Type	Size	D	E	A	H	OR O-RINGS
400	O.4617	3/8"	26	7,7	18	17	3068
400	O.4621	1/2"	31,8	7,7	24	19	4075
400	O.4627	3/4"	39,5	8,7	32	21	4100
400	O.4633	1"	47,6	9,5	38	25	4131
400	O.4642	1" 1/4	54	10,3	44	31	4150
400	O.4649	1" 1/2	63,5	12,5	51	33	4187
400	O.4660	2"	79,4	12,5	67	42	4225
400	O.4675	2" 1/2	94,2	16,5	80	47	6275
400	O.4690	3"	104	18	90	54	6300
400	O.4603	3" 1/2	119	20	102	54	6337
400	O.4615	4"	131	23,5	114	62	6350

Per ordinare coduli
How to order straight adaptors
Example pour commander collets
Bestellbeispiel für gerade adaptoren

Es.: O.....A
Es.: O.....B