



La massima pressione d'esercizio indicata in catalogo è basata sulla connessione a flangia.

The maximum recommended working pressure is based on the flange.

Serie 3000 psi

Pressione max esercizio bar	Tipo Type	Size S.A.E.	A GAS	I	K	E	H	M	N	OR O-RINGS
348	C.3001-90°-ORFS-A	1/2"	11/16"-16	6	30,2	6,7	22	44	50	4075
	C.3001-90°-ORFS-B		13/16"-16	9						
	C.3001-90°-ORFS-C		1"-14	12						
348	C.3002-90°-ORFS-A	3/4"	1"-14	12	38,1	6,7	27	53	64	4100
	C.3002-90°-ORFS-B		1 3/16 -12	15						
348	C.3003-90°-ORFS-A	1"	1 3/16 -12	15	44,4	8	34	60	65	4131
	C.3003-90°-ORFS-B		1 7/16 -12	20						
278	C.3004-90°-ORFS-A	1 1/4"	1 7/16 -12	20	50,8	8	42	55	64	4150
	C.3004-90°-ORFS-B		1 11/16 -12	26						
210	C.3005-90°-ORFS-A	1 1/2"	1 11/16 -12	26	60,3	8	50	66	78	4187
	C.3005-90°-ORFS-B		2"-12	32						

Serie 6000 psi

Pressione max esercizio bar	Tipo Type	Size S.A.E.	A GAS	I	K	E	H	M	N	OR O-RINGS
420	C.6001-90°-ORFS-A	1/2"	11/16"-16	6	31,8	7,7	22	44	50	4075
	C.6001-90°-ORFS-B		13/16"-16	9						
	C.6001-90°-ORFS-C		1"-14	12						
420	C.6002-90°-ORFS-A	3/4"	1"-14	12	41,3	8,7	27	53	64	4100
	C.6002-90°-ORFS-B		1 3/16 -12	15						
210	C.6003-90°-ORFS-A	1"	1 3/16 -12	15	47,6	9,5	34	60	62	4131
	C.6003-90°-ORFS-B		1 7/16 -12	20						
420	C.6004-90°-ORFS-A	1 1/4"	1 7/16 -12	20	54	10,3	42	70	72	4150
	C.6004-90°-ORFS-B		1 11/16 -12	26						
420	C.6005-90°-ORFS-A	1 1/2"	1 11/16 -12	26	63,5	12,5	50	80	84	4187
	C.6005-90°-ORFS-B		2"-12	32						

Per ordinare coduli a 90°:

How to order 90° adaptors:

Pour commander collet à 90°:

Bestellbeispiel für Gerade Adaptern 90°:

C.....90°-ORFS...ABC

C.....90°-ORFS...ABC

C.....90°-ORFS...ABC

C.....90°-ORFS...ABC

Su richiesta produciamo lo stesso codulo nella versione diritta

On request we can produce the same part straight

Sur demande nous produisons le même collet en la version droite

Auf Anfrage herstellen wir die gleiche Adapter gerade